

TECHNICAL & SAFETY COMMITTEE

INTERNATIONAL PARACHUTING COMMISSION (FAI)



Technical & Safety Information Notice No.	6/2008	W.N. 19
Date of Issue	23 September 2008	
Subject Matters	<p>1 <u>Use of Vigil II AAD in Dual Hawk Tandem System</u></p> <p>STRONG ENTERPRISES, Product Service Bulletin # 28, dated September 5, 2008.</p> <p>Strong Enterprises Service Bulletin # 28 authorises the use of VIGIL II AAD, date of manufacture 10/2007 or later, and Cutters, date of manufacture 11/2007 or later and when installation is accomplished according Dual Hawk Manual , P/N 510045, Rev. H. 05/08, Sec. 5.1 and Vigil ii instructions.</p> <p>Note - The Vigil II used in Dual hawk Tandem System shall only be used in Tandem mode.</p> <p>2 <u>RE-5L Emergency Parachutes, manufactured by SPEKON Sächsische Spezialkonfektionen GmbH</u></p> <p>EASA Airworthiness Directive, AD No. 2008-0174, dated 15 September 2008.</p> <p>SPEKON Safety Bulletin No. 01/2008, Issue 2.</p> <p>RE-5L Emergency Parachutes, series 4 and 5, from serial number 72245 up to 72369 inclusive, and 72371. These parachutes were manufactured between 21 April 2008 and 21 August 2008.</p> <p>One case of a cracked grommet has been found on the pilot chute of an RE-5L parachute. An internal review has revealed that drogue parachutes installed in RE-5L Emergency Parachutes series 4 and 5 as listed above, may present some crack initiations.</p> <p>This condition if left uncorrected could create an obstruction of the closing loop and prevent the main parachute from being pulled out of its storage pack.</p>	

	<p>For the reason described above, this AD mandates the replacement of the identified drogue parachutes.</p> <p>Effective date – 17 September 2008.</p> <p>Required actions and Compliance Times –</p> <ol style="list-style-type: none"> 1 Within 15 days after the effective date of this AD, replace the drogue parachute by a serviceable one as instructed in the SPEKON Safety Bulletin No. 1/2008 Issue 2. 2 After the effective date of this AD, no person shall install drogue parachutes removed per the requirements of paragraph 1 of this AD on any parachutes. To that end, conform to the applicable procedures about the control of unserviceable components. <p>Note – The RE-5L Emergency Parachute is an emergency parachute built for glider and motor pilots.</p> <p><i>Liam McNulty</i> IPC Technical & Safety Committee 23 September 200</p>
<p>Authorities</p>	<ol style="list-style-type: none"> 1 Strong Enterprises, 11236 Satellite Blvd., Orlando, FL 32837, USA. Tel. (407) 859-9317 ; Fax (407) 850-6978. 2 Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu <p><i>and/or</i></p> <p>SPEKON Sächsische Spezialkonfektionen GmbH, Nordstraße 40 – 02782 Seifhennersdorf, Germany Tel. +49 (0) 3586 456 0 Fax. +49 (0) 3586 456 167 E-mail – info@spekon.com</p>
<p>Acknowledgement</p>	<p>Thanks to the Australian Parachute Federation and to the Austrian Aero Club for bringing these two matters to the attention of the IPC Technical & Safety Committee</p>

Technical and Safety Information Notices issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as information and help to parachuting nations and their affiliated members. The Information Notices are of an objective informative nature and there is no direct or implied criticism of any manufacturer or product intended. The Information Notices do not claim to be complete.

The Information Notices may result from:-

- 1 An incident or experience in the field being reported.**
- 2 A directive or notice issued by an aviation or government authority concerning parachuting operations or parachuting equipment.**
- 3 The issue of a notice by a manufacturer or by a National Parachuting Organisation. In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.**

Technical & Safety Committee of IPC, IPC and FAI accept no liability for the use or misuse of any information contained in this Information Notice. The reader assumes all liability.

The Technical & Safety Committee, International Parachuting Commission, can be contacted on e-mail - lmcnulty@skydiveireland.ie

**Liam McNulty, Technical & Safety Committee, International Parachuting Commission.
18 July 2008.**